



# Quality Control Software



CREATE FORMS

1 group one

1.1 Reasons

Simple question does not integrate with any type of sub-measures

OPP Type 1 Uncondit

2 group two

2.1 Reasons

Question that allows adding sub-measures, usually related to interval values

OPP Type 2 Uncondit

Measures No. of changes allowed: 3

Point to Control	Lower limit	Upper limit	OK1st Part control medium	Production control medium
point 1	1.0	2.0	comparator	comparator

FULL CONTROL

Reasons: Start of shift Reference: 12345678TW

Subtitles Validation of the document

Point to Control	lower limit	Measured value	Upper limit	OK1 Part Control medium	Production control medium	OK	NOK	OPP
point 1	1.0	1.1	2.0	comparator	comparator	OK	NOK	OPP

3.1-Question that allows adding sub-measures, usually related to simple OK / NOK answer

Measures

measures 1	Aspect One	Aspect two	Aspect three	Aspect four
	OK NOK	OK NOK	OK NOK	OK NOK

Final result after confirmation of all points of the OK 1st Part form NOK COND GL

DATA REPORT

UAP: Select ... Line: Select ... Open date: 14/07/2020 Shift: T1 T2 T3 Reasons: Select ...

State: Select ... Reference: Select ... Closing date: dd/mm/yyyy

UAP	Line	Reference	Reasons	Open date	Closing date	Shift	Operator
UAP1	Prodline	12345678TW	Start of shift	14/07/2020 08:05	-	T1	qual
UAP1	Prodline	12345678TY	Reference Change + Qual	14/07/2020 11:35	-	T1	qual
UAP1	Prodline	12345678TY	End of shift	14/07/2020 15:45	-	T1	qual

## Answers

OPEN  
2

OK  
1

NOK  
0

## Forms

APPROVED  
35

EDITION  
609

PENDING  
2

TOTAL  
649

DEPRECATED  
3

TO APPROVE  
0



# Ok 1ª Peça

Quality Control Software


## Description

Quality inspection tool to control the conformity of the production process.

Used to control the first part produced after a relevant change in the process:

- Start of shift.
- Change of reference.
- Change of tools.
- Post repair of equipment.

Through the collection of process reference parameters, the system allows their validation (if they are within acceptable limits), keeping the record of inspections carried out for future proof.



# Ok 1ª Peça

Quality Control Software

## Functionalities

### Forms creation:

- Quick and intuitive creation of inspection forms.
- Form created by production reference, inspection reason and version.
- Several types of questions:
  - o OK / NOK.
  - o Value within predefined limits.
  - o Joint validation of several points.
  - o Answer with hidden reference value
- Complete cycle for forms approval (Quality, Production, ...).

### Forms usage:

- Automatically available forms (after approval and on the date of publication).
- Several alert solutions to request filling out the forms.
- Several alert solutions to report the lack of filling in the forms.

### Report and data exportation:

- Generation of multiple reports (Pareto diagrams, Last results, Capabilities, ...).
- Exporting data as Excel datasheet.
- Customizable dashboard updated in real-time (last notifications/alerts, aggregated data per product family/reference, ...).

# Ok 1ª Peça

Quality Control Software

## Functionalities

### Other features:

- Multiple users and profiles.
- Full management of users and profiles, integrated with LDAP.
- Automatic data backup.
- Measure instruments easily integrated into the system (dial indicators, micrometers, vernier, ...).



Brigantia Ecopark  
Av. Cidade de Leon, 506  
5301-358 Bragança  
Portugal  
[www.techwelf.com](http://www.techwelf.com)  
[geral@techwelf.com](mailto:geral@techwelf.com)  
Telephone: +351 273 310 382